

% How to Change Parameters Link - Search YouTube with the address or Kana tech team below https://youtu.be/yYrct017iyQ

Frequent alarm causes and countermeasures

| Alarm.                  | Cause  | countermeasure   |
|-------------------------|--|--|
| OC1,2,3 (overcurrent)   | Inverter output circuit short circuit ground                   | After disconnecting the secondary (motor) wiring of the inverter, only the inverter is operated. |
|                         |  | Check if an alarm is generated   |
|                         |  | - > If alarm does not occur: Check motor and wiring  |
|                         |  | - > When alarm occurs: Determining failure of inverter (request canaro inquiries)                |
| OL1 (motor overload)    | Large load (load above motor rating)                           | Eliminating causes of mechanical friction, jam, etc.   |
|                         | Nonconformity with electronic thermal settings                 | Compare F11 (Electronic Thermal Operation Level) to motor rated current                          |
|                         | Over-excitation during drive                                   | Change F37 (Talk Boost Selection) to 2 (Automatic)   |
|                         | - > The current goes up without going up to the set frequency. |  |
| OU1,2,3 (overvoltage)   | Short deceleration time or greater regeneration during braking | Set F08 (deceleration time) long   |
|                         |  | Check braking resistance for normal operation  |
| OH1 (cooling fan overhe | Ambient temperature is high                                    | Keep ambient temperature (in the panel) low (50C or less)  |
|                         |  | Check if the cooling fan is operating normally -> Replacement is required in case of abnormality |
|                         |  | Check that the exhaust direction of the cooling fan is not clogged with foreign substances, etc. |

## $\ensuremath{\mathbb{X}}$ If the alarm does not go off

- -> The reason why the alarm is not released after the alarm has occurred is that the abnormality of the alarm has not been resolved at the time the alarm has occurred.
  - If an alarm occurs, be sure to resolve the abnormality and release it with RESET. Power re-energization can cause inverter failure with the anomaly unresolved.

## **X** How to Initialize Parameters Factory

-> Select H03 parameter, change to STOP + arrow key to 1 and set to FUNC